


# **Transmission Line Model**

20181018 Mi Jang

Ohmic Contact Measurement



**1. Why is TLM required?**

**2. Principle of TLM**


**3. TLM process**

**4. How to measure Contact resistance**


# 1. Why is TLM required?

Current must flow in both direction  
between source and drain.

**Ohmic contact is very important!**



# 1. Why is TLM required?



Small region in the vicinity of the contact

$$R_c = \rho' \frac{\Delta x}{A_c}$$


$$\rho_c = \lim_{\Delta x \rightarrow 0} (\rho' \Delta x) = R_c A_c$$

$A_c$ : Contact area

$R_c$ : Contact resistance

$\rho_c$ : Contact resistivity

# 1. Why is TLM required?



$$R_T = \cancel{2R_m} + 2R_c + R_{semi}$$

Values caused by contact

Metal has very low resistivity


$$R_{semi} = R_s \frac{L}{W}$$

$$R_T = \frac{R_s}{W} L + 2R_c$$

Contact resistance may be obtained by measuring the total resistance.

## 2. Principle of TLM

### Current Crowding



The physical length and width of the electrode should not be used directly to determine the contact resistance.



Effective area of contact:  $L_T$

Called by transfer length


$$R_c = \frac{\rho_c}{L_T W} = \frac{R_s L_T}{W} \star$$

## 2. Principle of TLM


$$R_T = \frac{R_s}{W} L + \underline{2R_c}$$

$$R_T = \frac{R_s}{W} L + 2 \frac{R_s L_T}{W}$$

$$R_T = \frac{R_s}{W} (L + 2L_T)$$






# 3. TLM process





# 3. TLM process



Mask pattern for mesa etching





FIGURE 3.2: Schematic of TLM test structure

# 3. TLM process

## Metal Alloying




Work function is vital factor in ohmic contact!




- Reduction of work function
- Increase of conductivity

# 3. TLM process

Role of Metal	
Aluminum (Al)	Gold (Au)
<ul style="list-style-type: none"><li>It is easy to deposit thin films of Al by vacuum evaporation.</li><li>It has good adherence to the silicon dioxide surface.</li><li>It forms good mechanical bonds with silicon by sintering at about 500°C or by alloying at the eutectic temperature of 577°C.</li><li>It forms low-resistance contacts with p-type silicon and with heavily doped n-type silicon.</li></ul>	<ul style="list-style-type: none"><li>It improves ohmic contacts conductivity.</li><li>It prevents oxidation for other metals during high annealing temperature.</li></ul> 
<ul style="list-style-type: none"><li>During packaging operation if temperature goes too high, say 600°C, or if there is overheating due to current surge, Al can fuse and penetrate through the oxide to the silicon and may cause short circuit in the connection.</li></ul>	<ul style="list-style-type: none"><li>It acts as a deep level trap and recombination center, i.e. charge carriers of opposite sign do recombine at Au defects in Si and get lost to the current.</li><li>It has poor adhesion.</li></ul>

# 4. How to measure Contact resistance

2 point probing



2 point probing

## ❖ Advantages

- Easy to measure contact resistance

## ❖ Disadvantages



- Lots of assumptions
- Low accuracy

# 4. How to measure Contact resistance


4 point probing



The elimination of resistances between contact and wire



# 4. How to measure Contact resistance



Mask pattern for mesa etching

$$R_c(\text{ohm} \cdot \text{mm}) = R_c(\text{ohm}) \times \text{width}$$

**Thank you for hearing my TLM presentation!**